



THIS IS TO CERTIFY THAT

Baumer A/S

Jacob Knudsens Vej 14, DK-8230 Aabyhoj, DENMARK

is hereby authorized to continue to apply the
3-A Symbol to the models of equipment, conforming to 3-A Sanitary Standards for:

Sensors and Sensor Fittings and Connections, Number: 74-03

set forth below

FlexBar / CombiTemp Accessories, 8126 - 916; Welding part 3A / DN76, 8126 - 919; FlexBar Accessories, 8126 - 925; CombiTemp Accessories, 8126 - 938; CombiTemp Accessories, 8126 - 939; InLine Pipe, 8126 - 944; InLine Pipe, 8126 - 945; InLine Pipe, 8126 - 946; InLine Pipe, 8126 - 947; InLine Pipe, 8126 - 948; InLine Pipe, 8126 - 949; Temperature Transmitter, 814x D, H and I; FlexBar HRT. DN38 Clamp ISO 2852, 816x xxxx x4xx; FlexBar HRT. DN51 Clamp ISO 2852, 816x xxxx x5xx; FlexBar HRT. DN38 3A Hygienic Connection, 816x xxxx x6xx FlexBar HRT. DN76 3A Hygienic Connection, 816x xxxx x7xx; FlexBar HRT. M44 x 1.25 Male Nipple. Hygienic Connection, 816x xxxx xFxx; FlexBar 3431. DN38 Clamp ISO 2852, 3431-xxxx-x4xx; FlexBar 3431. DN51 Clamp ISO 2852, 3431-xxxx-x5xx; FlexBar 3431. DN38 3A Hygienic Connection., 3431-xxxx-x6xx; FlexBar 3431. DN76 3A Hygienic Connection., 3431-xxxx-x7xx; FlexBar 3431. M44 x 1.25 Male Nipple. Hygienic Connection, 3431-xxxx-xFxx; CombiTemp. DN38 3A Hygienic Connection, 814x Dxxx xxxx xxx xxxx; CombiTemp. DN38 3A Hygienic Connection. Surface Sensor, 814x Exxx xxxx xxx xxxx; CombiTemp. DN38 Clamp ISO 2852, 814x Hxxx xxxx xxx xxxx; CombiTemp. DN51 Clamp ISO 2852, 814x lxxx xxxx xxx xxxx; Level Switch, LFFS xxxx; FlexBar / CombiTemp Accessories, 8126 - 928; Level Switch, LBFS xx4x x; PFMH-XXXX-XXXX; ISL 05x Inductivi Conductivity Transmitter, ISL 052 x; LSP 05x Potentiometric Level Transmitter, LSP 05x xxx x xxx; LSK x2x Conductive Level Sensor, LSK x2x xxx x; LSK x5x Conductive Level Sensor, LSK x5x xxx xxx xxx xxx x; TE1-Temperature with Field Housing, TE1x 7xxx xxxx xxxx; TE1-Temperature with Field Housing, TE1x 8xxx xxxx xxxx; TE1-Temperature with Field Housing, TE1x 9xxx xxxx xxxx; TE1-Temperature with Field Housing, TE1x Axxx xxxx xxxx; Accessories. Clamp DN38 ISO 2852, CAM 0X3-505, M12 1/2 in. - 1 in.; Accessories. Clamp DN51 ISO 2852, CAM 0X3-640, M12 1/2 in. - 1 in.; Accessories. GEA Tuchenhagen Varivent, VAM 0x3, 1/2 in. - 1 in.; ISL 05x Inductivi Conductivity Transmitter, ISL 052 x; LSP 05x Potentiometric Level Transmitter, LSP 05x xxx x xxx; LSK x2x Conductive Level Sensor, LSK x2x xxx x; LSK x5x Conductive Level Sensor, LSK x5x xxx xxx xxx xxx x; TE1-Temperature with Field Housing, TE1x 7xxx xxxx xxxx; TE1-Temperature with Field Housing, TE1x 8xxx xxxx xxxx; TE1-Temperature with Field Housing, TE1x 9xxx xxxx xxxx; TE1-Temperature with Field Housing, TE1x Axxx xxxx xxxx; Accessories. Clamp DN38 ISO 2852, CAM 0X3-505, M12 1/2 in. - 1 in.; Accessories. Clamp DN51 ISO 2852, CAM 0X3-640, M12 1/2 in. - 1 in.; Accessories. GEA Tuchenhagen Varivent, VAM 0x3, 1/2 in. - 1 in. Accessories. Weldings Sleeve, PM 0xx, M12 1/2 in. - 1 in.

Timothy R. Rugh
Executive Director, 3-A Sanitary Standards, Inc.

The issuance of this authorization for the use of the 3-A Symbol is based upon the voluntary certification, by the applicant for it, that the equipment listed above complies fully with the 3-A Sanitary Standards designated. Legal responsibility for compliance is solely that of the holder of this Certificate of Authorization, and 3-A Sanitary Standards, Inc. does not warrant that the holder of an authorization at all times complies with the provisions of the said 3-A Sanitary Standards. This in no way affects the responsibility of 3-A Sanitary Standards, Inc. to take appropriate action in such cases in which evidence of nonconformance had been established.

NEXT TPV INSPECTION/REPORT DUE: **July 2014**